





Storage tank - maintenance:

Tank base corrosion
Bonding Applications
Corrosion protection External Internal

API 653: Tank lifting as an option to repair

Prepared by: DSc Dževad Hadžihafizović (DEng)

Sarajevo 2023

MONTHLY ABOVEGROUND STORAGE TANK INSPECTION CHECKLIST

ocation:	Date:	Completed by:
----------	-------	---------------

	Tank:	Tank:	Tank:
Is there any deterioration on the tank, tank coating, piping, foundation, drainage, supports, ladder,		Yes	Yes
platform, or safety equipment? For molded plastic tanks, check for evidence of cracked and worn areas and delamination. If yes, specify below.	No	No	No
Is there any water at the lowest possible point within the primary tank (fuel tanks only)? Remove	Yes	Yes	Yes
any water found. For tanks containing other products, is there any evidence of chemical		No	No
degradation?	N/A	N/A	N/A
Is there any evidence of liquid (product or water) in the interstitial space (double-walled tanks) or	Yes	Yes	Yes
containment area?	No	No	No
	N/A	N/A	N/A
Are all drain valves secured in the closed position when not in use and all tank openings properly	Yes	Yes	Yes
	No	No	No
sealed? Are the piping connections tight and aligned?	N/A	N/A	N/A
	Yes	Yes	Yes
Is the spill basket clean and functional?	No	No	No
	N/A	N/A	N/A
Is the liquid level gauge readable and in good condition?	Yes	Yes	Yes
is the liquid level gauge readable and in good condition:	No	No	No
Are there any obstructions or restrictions to the normal and emergency vents that prevent normal	Yes	Yes	Yes
function? Ensure that the emergency vent moves freely.	No	No	No
Are there any operational malfunctions of ancillary equipment (pumps, gauges, etc.)?	Yes	Yes	Yes
Are there any operational manufictions of anchiary equipment (pumps, gauges, etc.):	No	No	No
Is there any evidence of a release from the tank – this includes visible signs of leakage around the	Yes	Yes	Yes
tank, concrete pad, containment area, ringwall, or ground?	No	No	No
Is there a clear path to the tank and containment area, and are gates/doors to the containment area	Yes	Yes	Yes
operable and in good condition?	No	No	No
Is a complete spill kit available?	Yes	Yes	Yes
Is a complete spill kit available?	No	No	No
Are there any conditions that may be a fire or safety hazard, or pose an environmental hazard? If	Yes	Yes	Yes
yes, specify below.	No	No	No

Any deficiencies noted during the inspection must be corrected as soon as possible	e. Facility personnel must contact EHS to review all tank maintenance
and needed repairs with the exception of replacing hoses and fuel filters	. If there are any questions, call the Department of Environmental Health and
Safety at 814/865-6391. Comments/Clarifications and Corrections:	





Belzona Solutions Storage Tanks

Outline



- Overview of a Storage Tank
- Storage Tank Problem Areas
- Belzona Solutions for Storage Tanks
 - Overview
 - Tank base corrosion
 - Bonding Applications
 - Corrosion protection
 - External
 - Internal



Overview of a Storage Tank

What is a Storage Tank?



- A storage tank is a bulk storage container usually for holding liquids, sometimes for compressed gases
- are 6 of these tanks!
 Storage tanks are available in many shapes
- Some of the largest can be found in Zirku island in the UAE.
 They can hold 1.25m barrels of oil...



What is a Storage Tank?



- One of the most common types of storage tank in industry are cylindrical storage tanks
- These can be used to store a variety of materials



Storage Tank Types



Variable Vapor Space Tank

Five main types of cylindrical storage tank:

- 1. Fixed Roof Tank
- 2. Internal Floating Roof Tank
- 3. External Floating Roof Tank_
- 4. Open Top Tank
- 5. Pressurized Tank

Fixed Roof Tank Overview



- For storing harmless liquids involving little or no pressure, and very high flash points. (e.g. fuel oil, water, bitumen etc.)
- Simple, mild steel, rectangular or cylindrical tanks fitted with a flat, dome or conical roof.






Floating Roof Tank Overview




- Variable Volume Tanks
 - Internal Floating Roof Type




External Floating Roof Tank (FRT)





Internal Floating Roof Tank (IFRT)





Other Tank Types



Open top tank -

Pressurised Tanks







Storage Tank Problem Areas

What is the Problem?



Leaks leading to

- Wastage
- Lost resources
- Environmental damage
- Potential disaster





"Statistics indicate as many as 25% of all Underground storage tanks (USTs) may now be leaking"

Maryland Real Estate Agency

"Almost 10,000 gasoline and oil spills, some of them more than a decade old, are contaminating the underground aquifers that supply drinking water" Scientific Journal

What is the Problem?



Corrosion is the main cause of these leaks



Other causes could be environmental damage or damage due to impact






Belzona Solutions For Storage Tanks

Belzona Solutions

Overview






Belzona Solutions


Overview





Problem Areas Tank Base





orrosion of tank wall and line angle Water / moisture ingress under the tank base through etesiorationeoftsealnk moves the capillary action squeezes the water under offesion of tank base

Tank Base Traditional Repairs





- Mastics
- Asphalt & Bitumen

Problem Areas Tank Base





Steel Skirts

Problem Areas Tank Base





Bonded Rubber

Problem Areas

Tank Base



Corrosion at the Chine Angle

- Tank needs to be cut open for plate entry
- New base needs to be built
- Base welded into position
- Hydro Test needs to be conducted

Approx. Costs (30 Metre tank)

- £20,000 for cutting and entry / base removal
- £4,000 for sand-bit floor screed replacement
- £5,000 for flexible liner
- £20,000 for new bottom plates
- £50,000 for inspection and Hydro Test

£99,000

Plus:

- Tank cleaning / waste disposal costs
- Tank out of service for 3 months







Tank Base Sealing using Belzona

Belzona System Advantages



What makes the Belzona system better?

- Breathable
- Flexible
- Weather resistant
- Excellent adhesion...

Weatherproof Prevents water penetration



Microporous Allows moisture to escape



Seamless Seals around irregular contours



High adhesion Ensures long service life onto a variety of surfaces



Durable Withstands industrial environments



Environmentally friendly Low VOCs



Surface tolerant Good adhesion to a variety of surfaces



Longevity Stands the test of time



Flexible Moves in sympathy with the substrate



UV resistant Resists climatic variations



Cold applied Safe





- Surface Preparation by grit blasting
- Conditioning using Belzona Surface Conditioners
- 3. First layer of Belzona 3111
 Flexible Membrane and
 Belzona 9311
 Reinforcement Sheet
- 4. Final Layer of Belzona 3111 for full system.



1. Surface Preparation by grit blasting



- Grit blasting to 75 micron profile on the steel tank wall & tank base
- Pit filling using a Paste grade product or plate bonding if necessary on the tank outside walls
- Rebuilding of the concrete base with a Belzona 4000 series product if heavily damaged



2. Conditioning using Belzona 3921 General Surface Conditioner (GSC)



Belzona 3921 GSC is applied on all the areas where the system is to be applied

Bond breaker tape is applied between the metal surface and the base

Masking tapes keep the application neat and tidy



3. First Layer of Belzona 3111 and Reinforcement sheet



 Application of the first Belzona 3111 layer can commence when the Belzona 3921 has cured (at least 4 hours, no more than 2 days)



 Reinforcement sheet is used to control application thickness and provide strength and flexibility



4. Application of final layer of Belzona 3111




- Application of the final second layer of Belzona 3111
- The complete system fully seals the tank base



Belzona Solutions Overview





Welding or Bonding?






Forces are transferred through the HEAT AFFECTED zones <u>only</u>

Welding or Bonding?





100% contact so, forces are transferred through the ENTIRE BONDED AREA

Plate Bonding Advantages



- Very High Adhesion
- Impressive Impact Resistance
- Easy to do on site technology developed for use offshore
- No welding or similar problems
- Tried and tested solution...
- Compared to original 8mm deck, the composite plate can withstand greater static loading and higher impact loads before failure
- In shear the composite sandwich is comparable to an equivalent weld
- The composite sandwich provides the most reasonable compromise between cost and performance. It is considered robust enough to withstand the rigours of laydown area operations



Bonding Applications



- A versatile and effective solution to many common problems
- Not limited to plate bonding for leak sealing...



Bonding Applications



Leak sealing is one of the main reasons for carrying out plate bonding operations



Bonding Applications





Bonding Applications



- Bonding applications are not just confined to leak sealing and corrosion protection
- Supports, walkways, stairs and lifting equipment can also be bonded using the same technique



Other Bonding Applications



Bonding can also be used to attach many other pieces of equipment such as...



Stairways and walkways...



Wind Girders...



Deluge systems...

Other Leak Sealing Applications



Leak sealing of a floating roof - just like any equipment which floats, if a leak occurs in a floating roof, it could sink!






Internal and External Tank Linings


Why Think About Lining Any Tank?


BELZONA®
Repair • Protect • Improve


Limitations of Conventional Materials of Construction

- Carbon Steel
- Overlaid Carbon Steel
- Stainless Steel
- Duplex Steels

















Tank Construction Considerations



Riveted or Welded seams?

- Check radii prior to application
- Grind smooth any irregularities
- Use a paste grade product to smooth and fair surface irregularities







Internal and External Linings Application Method




Application Method:

- Grit Blast steel
- Check for contamination
- Pit filling
- Stripe coating
- First coat application
- Second coat application
- Final inspection



Belzona Solutions Overview





External Protection Belzona 6111/5111



External corrosion can lead to thinning of the tank walls and potential leaks


- Grit blast steel
- Fill in pitting if necessary
- Apply Belzona 6111 Liquid Anode for steel protection
- Apply two coats of Belzona 5111
 Ceramic cladding



Result is not only corrosion protected but is also stain and UV resistant and aesthetically pleasing

Belzona Solutions Overview





Product RangeInternal Lining Products



Product Reference Belzona pr	Operating temperature Toduce a large re	Sprayable ange of Inte	Spark & thickness rnælstætileg	Chemical resistance solutions. Th	Erosion resistant e choice
of product	depends on the	application	situation. D	o you requir	e _{No}
• 13bemic	algesis(temce?	No	No	excellent	Yes
• Aspray			Yes	limited	Yes
Fresion	mperature resis	tance? Yes	Yes	excellent	No
+ Erosion 5891	90°C (194°F)	Yes	Yes	good	No
1391S	110°C (230°C)	Yes	Yes	excellent	No
1391	120°C (248°F)	No	No	good	Yes
1391T	120°C (248°F)	No	Yes	excellent	Yes
1392	120°C (248°F)	No	No	excellent	Yes
1521	150°C (302°F)	Yes	Yes	excellent	No
1591	180°C (365°C)	No	Yes	excellent	Yes

Product Range

Internal Linings for Service Below 90°C







- Belzona 1321 (Ceramic S-Metal)
- Belzona 1341 (Super metal Glide)
- Belzona 4311 (CR-1)
- Belzona 5811 (Immersion Grade)
- Belzona 5891 (High Temperature Immersion Grade)
- Belzona 5892 (High Temperature Immersion Grade 2)








Application

Internal Linings for Service Below 90°C



Crude oil storage tanks in Brazil.



Product Range

Internal Linings for Service Above 90°C









- Belzona 1391 (Ceramic High Temperature)
- Belzona 1391T (Trowel able grade)
- Belzona 1391S (Spray applied version of Belzona 1391)
- Belzona 1392 (Ceramic High Temperature 2)
- Belzona 1521 (High Temperature Spray Applied Coating)
- Belzona 1591 (Ceramic Extreme High Temperature Coating)







Application

Internal Linings for Service Above 90°C BD



- Corrosion in the tank base
- Only the problem areas were coated saving time and money
- Belzona 1521 was chosen for it's resistance to hydrocarbons, spray capabilities and performance in hot water/ hydrocarbon situations



Belzona Solution

Corrosion Protection of small bore nozzles









Major Opportunity Worldwide





Ivor Wildin Director, WTS





API 653: TANK INSPECTION CODE:

TANK LIFTING AS AN OPTION TO REPAIR

©2010 Worldwide Tank Services. This document is the property of Worldwide Tank Services. No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without the prior written permission of Worldwide Tank Services









Introduction

General

Annex B of API 653 lays out prescriptive limits to bottom settlement, planar tilt and differential settlement. If the settlement is found to be outside the stated limits what options do we have to correct it?



OPTIONS FOR LIFTING TANKS

- 1. AIR BAGS
- 2. CLIMBING JACKS
- 3. HYDRAULIC JACKING



Are the most common forms of lifting storage tanks however both Option 2 & 3 require the welding on of lifting frames or pad eye to connect the jacks to. If a tank has leaked and washed out the basecourse then it would not be prudent to weld in the vicinity.



AIR BAG LIFTING

Within the past five - ten years the environmental impact on the operation of petro-chemical product storage tanks containing hydrocarbon or other dangerous goods, constructed to standards such as API 650, has taken on critical implications for refineries, distribution centres and other storers of Dangerous Goods.



Pollution of the supporting foundation and possible widespread effects on ground water has resulted in moves to require the installation of secondary containment. That is not to say, necessarily, a tank with two steel bottoms, but alternative means of reducing the failure probability to an acceptable public or statutory level. Compliance with statutory codes such as Dangerous Goods Regulations 2010 and AS 1940 dictate that 'impervious' secondary containment is now required throughout the bunded area.

In the USA, Europe, and other western countries it has long been required to also place a secondary containment liner or double bottom under storage tanks.



The ongoing quest by engineers is to establish corrosion trends in tanks through inspection by various means however the underfloor has always provided a challenge to ascertain a clear evaluation of deterioration hence, assurance of the integrity of the primary containment.

Clearly, increased inspection of the tank bottom has merit and visual examination of the bottom from inside the tank can be supplemented by ultrasonic methods, acoustic leak detection and magnetic flux scanning.



Tank lifting now offers a very cost-effective method for underfloor inspection, combined with the opportunity to undertake repairs to the bottom and underside painting, together with improvements and repairs to the Bit-sand surface of the tank pad.

An impervious membrane can also be installed with a leak detection trough formed around the tank edge so rendering the tank compliant and extending its useful life.





















In fact, tank lifting using discrete airbags offers the most cost-effective method for lifting tanks off their foundations. When compared with the more conventional system of hydraulic jacking, the airbag method results in some very distinct advantages, apart from a most significant reduction in cost.



It is not necessary to weld any attachments to the shell or dig deep pits beneath the annular plate. Site preparation is an absolute minimum, and only requires excavations extending 400mm, under the tank shell by 800mm wide and 30mm deep, at a number of discrete locations. In the case of smaller tanks, say up to 46M (150 feet) diameter, the annular plate can be well clear of the pad within six hours of the lifting crew arriving at site.



Summary

The application of the airbag method for lifting bulk liquid storage tanks has been described, together with some of the background theory and experimental measurements that have been made to develop a safe and very economical means of raising tanks so that their bottom underside can be examined or foundation pad repaired or complete secondary containment inserted under the tank.

NDT methods are always a 'compromise' and address the evaluation of a defect but not the 'root cause' or seek to remediate the cause, this can lead to defects caused by foundation debris continuing to manifest themselves in the corrosion of repaired plates on a floor.



Other considerations are those causing settlement problems in storage tanks where the ground bearing capacities have not resisted the forces applied by the tank. Planar tilt and differential settlement render the tank unusable if this exceeds the limitations in Appendix B of API 653. The lifting of the tank either partially or wholly to insert a ring beam (FIG 1) is required to remediate the settlement.

WORLDWIDE TANK SERVICES












Size Limits?



53 X 19M **SRC Singapore**




Other touches we can do:





This tank had leaked twice at SRC Singapore and the floor was to be replaced. After lifting it was found that the MFL Scan was in error and there was only two holes in the floor due to stones the rest of the floor had the heat numbers still visible in perfect condition!



25M X 15M **SRC Singapore**




The finishing touches...





HMAS Stirling WA





FLOOR CHANGE AUSTRALIAN LUBRICATION MANUFACTURERS FREMANTLE, WESTERN AUSTRALIA

WORLDWIDE TANK SERVICES

A JOINT CALTEX/BP FACILITY



Tank 21 at ALMC had suffered planar tilt outside the limits stated in API 653 Appendix B. The tank was built in 1938 and had leaked through external floor corrosion.

The job was to correct the differential settlement, install a secondary containment liner under the tank and change the floor in the tank.







The tank was lifted from the ground using airbags inserted under the tank







As the tank rises pushed up by the airbags the height gain is consolidated by inserting timber gluts under the tank. The number anf support and lifting positions is dictated by a computer program which ensures the stability of the tank and that the compressive loads do not exceed the bottom strake buckling (API 650) of the tank.













The lifting continues around the tank until the whole periphery of the tank is supported on the cribs of timber













As the tank rises the airbags are placed on cribs of timber which then allows the tank to be lifted increasingly higher. The height gain is constantly consolidated by inserting further timber gluts on the support cribs. The tank always remains LEVEL +/- 6 inches side to side minimising any stresses imposed in the lifting.













Upon attaining access height under the tank the lifting cribs are removed and the basecourse foundation cap is taken out. This particular tank dihedral of the floor was changed from Cone-Up to 1:120 Cone Down....hence further excavation was required. The concrete ring beam was not level which accounted for the tank differential settlement.








Formwork was laid out to pour the increase in height of the ringbeam and level the tank







After filling of the basecourse it was now time to place in the secondary containment. A drain pipe was incorporated in the basecourse to allow draining in the event of a release under the tank.

























Geotextile and pea gravel is added to ensure free drainage in the secondary containment sump







Formwork is added to the sump to ensure the correct dihedral of the resulting fill of the basecourse. The basecourse is now ready for final fill and compaction. The new floor will also be laid on the basecourse



















The new sump is added to the floor and welded into place













Lifting cribs are re-inserted around the tank and the tank is lowered













The tank remains at 6 inches above the new floor to allow the cutting out of the old floor








The old floor is cut out and pulled out from under the tank. Sidewalls are cut above the HAZ and the sketch plates released from the tank. The tank is the differentially lowered setting the sidewall onto blank nuts to ensure the roundness of the tank is maintained.

























The setting of Blank Nuts (44 - 46) allow us to ensure that the tank wall is on the scribe line and can be adjusted by the insertion of the carrot pins (taper wedges - 52) ensuring the tank remains 'round'.



The tank can now be welded in the normal way and the floor welded internally.

The tank will then be boxed up and hydrostatically tested and certificated to API 653



TANK LIFTING FOR FLOOR **REPACEMENT**



WORLDWIDE TANK SERVICES

SPECIALIST INSPECTION LIFTING AND RELOCATION OF BULK STORAGE TANKS 1, FORBES ROAD MANDURAH WESTERN AUSTRALIA TEL. (61) 8 9535 8176 MOB 0439 913313

> MAJOR BULK TANK INSPECTION **CATEGORY 5 & 6 ABOVEGROUND TANK** FINAL INSPECTION AND FIELD REPORT AFTER MAJOR REPAIR

welds, 100% Magnetic Particle Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flo inter-plate welds Bulk Tank Data Sheet attached YES/NO See MDR File Overall Roof Condition from visual inspection: Good NDT: See MDR File Overall Shell Condition from visual inspection: Good NDT: See MDR File NDT inspection by: Are NDT Reports Attached: YES / NO See MDR File NDT test date: December 2012 – See MDR Report Statutory Inspection to AS 1940 – API 653 4 th Edition Addendum 2 Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishmen included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam, Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compaction of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a centre sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostate test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No			
Australasian Lubrication Manufacturing Company Swan Street North Fremantle Western Australia Date(s) of Inspection conducted on 13 th December 2012 after levelling of tank, new floor bottom plates and installation of secondary or containment liner / leak detection. Design Pressure Atmospheric Atmospheric Base Oil Product Stored: Base Oil NDT: See MDR File Overall Shell Condition from visual inspection: Good NDT: See MDR File Overall Shell Condition from visual inspection: Good NDT: See MDR File NDT inspection by: Are NDT Reports Attached: YES / NO See MDR File NDT rest date: December 2012 – See MDR Report Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishmen included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam, installation of a HDPE 1.5m sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat least of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of the other tank repairs required? No	Tank No. ALMC T21		Unit/Location: North Fremantle Lube Plant
Final Inspection conducted on 13th December 2012 after levelling of tank, new floor bottom plates and installation of secondary containment liner / leak detection. Internal — External Inspection, NDT conducted on new flowelds, 100% Magnetic Particle Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds, 100% Magnetic Particle Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds, 100% Magnetic Particle Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds Internal/External Inspection of Annular Fill Welds Internal/External Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Bulk Tank Data Sheet Internal External Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection in Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection for Melds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection for Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection internal External Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowelds. Internal — External Inspection internal External Inspection of Annular Fill Welds Internal/External and 100% Vacuum Box Testing of flowe	Australasian Lubrication Swan Street North Fremantle	on Manufacturing Company	
attached YES/NO See MDR File Overall Roof Condition from visual inspection: Good NDT: See MDR File Overall Shell Condition from visual inspection: Good NDT: See MDR File NDT inspection by: Are NDT Reports Attached: YES / NO See MDR File NDT test date: December 2012 – See MDR Report Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishmen included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam. Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compection of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a centre sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No	Final Inspection conduction of tank, new floor botto	m plates and installation of seconda	Internal – External Inspection, NDT conducted on new floor welds, 100% Magnetic Particle Inspection of Annular Fillet Welds Internal/External and 100% Vacuum Box Testing of floor
Overall Roof Condition from visual inspection : Good NDT: See MDR File Overall Shell Condition from visual inspection: Good NDT: See MDR File NDT inspection by: Are NDT Reports Attached: YES / NO See MDR File NDT test date: December 2012 – See MDR Report Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service.	attached YES/NO		Stored:
NDT inspection by: Are NDT Reports Attached: YES / NO See MDR File NDT test date: December 2012 – See MDR Report Statutory Inspection to AS 1940 – API 653 4 th Edition Addendum 2 Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishment included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam, Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compection of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a centre sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No		om visual inspection : Good	NDT: See MDR File
Are NDT Reports Attached: YES / NO See MDR File NDT test date: December 2012 – See MDR Report Statutory Inspection to AS 1940 – API 653 4 th Edition Addendum 2 Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishment included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam. Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compaction of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a centre sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No	Overall Shell Condition fr	om visual inspection: Good	NDT: See MDR File
December 2012 – See MDR Report Addendum 2 Comment on overall tank condition: Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishmet included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam. Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compaction of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a centre sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No		ed: YES / NO See MDR File	(Company) Marine Inspection Services P/L
Tank 21 is in good condition, compliant with AS 1940 and API 653 and considered fit for service. Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishment included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam, Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compaction of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a centre sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No		IDR Report	Statutory Inspection to AS 1940 – API 653 4 th Edition Addendum 2
Tank 21 was refurbished after being identified with a lean exceeding the confines of Annex B of API 653. The refurbishmen included the lifting of the tank off its base to 1.8M, recapping and levelling the concrete ring beam, Installation of a HDPE 1.5m secondary containment Liner with leak detection piping, filling and compaction of basecourse foundation over liner, installation of new floor bottom plate 8mm W.T – reversing the cone of the floor from the original cone up to a cone down 1:120 slope to a central sump with water drain piping. Extensive NDT was conducted on the repairs in keeping with the confines of both API 653 and API 650 including a full hydrostat test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No			22.1 18 1888 1888 18
test of the tank as per the requirements of API 650 with a hold time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage of settlement was observed. Are other tank repairs required? No	Tank 21 was refurbishe included the lifting of the secondary containment L new floor bottom plate 8n	d after being identified with a lean of tank off its base to 1.8M, recapping liner with leak detection piping, filling mm W.T – reversing the cone of the file	exceeding the confines of Annex B of API 653. The refurbishment and levelling the concrete ring beam, installation of a HDPE 1.5mm and compaction of basecourse foundation over liner installation of a
Account of the Control of the Contro	test of the tank as per the settlement was observed.	requirements of API 650 with a hold	the confines of both API 653 and API 650 including a full hydrostatic time exceeding 24hrs on 12 th – 13 th December 2012 – No leakage or
Duty-of-service maintenance required? No	Are other tank repairs req	uired? No	
Set of Set free members required in the	Out-of-service maintenan	ce required? No	

Tank Inspection Completed by an Approved Tank Inspector:

Signed:

Name: Ivor P Wildin

API 653 Reg. Inspector Name: Ivor P Wildin API Registration Number Reg Inspector 1246 Inspection Closeout Date:

FIT FOR SERVICE / NOT FIT FOR SERVICE