



45TH TURBOMACHINERY & 32ND PUMP SYMPOSIA
HOUSTON, TEXAS | SEPTEMBER 12 – 15, 2016
GEORGE R. BROWN CONVENTION CENTER

Thermal Load Effect on Vibration on a Reactor Feed Water Pump (FWP)

By:



Maki M. Onari
Sr. Principal Engineer
Manager of Turbomachinery Testing
11 Apollo Drive
Whippany, NJ 07981
Tel: (973) 326-9920
maki.onari@mechsol.com



TEXAS A&M[®]
UNIVERSITY





45TH TURBOMACHINERY & 32ND PUMP SYMPOSIA
HOUSTON, TEXAS | SEPTEMBER 12 – 15, 2016
GEORGE R. BROWN CONVENTION CENTER

Maki M. Onari:

- Mechanical Solutions, Inc. – Manager of Turbomachinery Testing Sr. Principal Engineer: responsible for all MSI Turbomachinery Testing
- B.S.M.E., Zulia University, Venezuela
- Rotating Equipment Engineer, PDVSA: responsible for the predictive maintenance of one of the largest petrochemical complexes in Latin America
- Co-Author Pump Vibration Chapter, McGraw-Hill Pump Handbook
- Member of ASME and the ISO TC108/S2 Standards Committee for Machinery Vibration
- Presented tutorials, case studies, and lectured at the Texas A&M Symposia since 2007 as lead instructor on vibration short courses.



TEXAS A&M[®]
UNIVERSITY



General Information

Constellation Energy – Exelon Corp.

Nine Mile Point Nuclear Station (NMPNS) Unit 2 – 1150 MW (Oswego, NY)

Application:	Reactor Feed Water Pump (FWP)
Type:	20x20x22 – 2 Stage (barrel type radial split)
Capacity:	8,000 gpm (min flow) to 22,870 gpm (max flow) Normal operation steady slightly above BEP
Suction Press.:	550 psig
Discharge Press.:	1,200 psig
Speed:	3,339 rpm (55.7 Hz)
Temperature:	382 °F
Normal Load:	10,500 to 11,500 BHP
Driver:	Induction Motor (16,500 HP @ 1785 rpm (29.8 Hz))
Gearbox:	Speed Increaser (Gear ratio 1:1.87)




GEORGE R. BROWN CONVENTION CENTER

September 12 -15.2016

Background

Repetitive failure mechanical seals since 1987 (MTBF of 6 months on Alpha FWP). Possible axial shuttling of the pump rotor




Analysis performed by the OEM, the pumps required a series of modifications to improve seal reliability and also increase plant capacity by 15% Extended Power Upgrade (EPU)

Former Design Cross Section
20x20x22 – 2 Stage

Background

FAT vibration on the order of 1.0 to 1.5 mils pk-pk


June 2010: High synchronous vibration was detected only at the IB end of the pump shaft (over 4.2 mils pk-pk).




Modified in Spring 2010

Initial Testing June 2010


2FWS-P1A Pump Typical FRF Plots



Horizontal Direction




Axial Direction




Vertical Direction


2FWS-P1A Pump Main Mode Shapes




Lateral Rocking Mode @ 44 Hz



Twist Mode @ 89 Hz




Axial Rocking Mode @ 59.3 Hz





OBB Vertical Mode @ 395 Hz

Continuous Monitoring (CM) Testing



Pump Shaft Vibration


Pump IBB Radial Proximity Probes Overall Pk-Pk Vibration



Shaft vibration mostly at 1x rpm
Bearing housing vibration was acceptable




Pump Shaft Vibration

Pump OBB Radial Proximity Probes Overall Pk-Pk Vibration




Shaft vibration mostly at 1x rpm
Bearing housing vibration was acceptable

Orbit Plots 20,000 GPM @ 3:56, 6-13-2010




* View from pump end unless otherwise stated

ODS Animation at 1x rpm



Possible Causes...



- Misalignment: Severe offset misalignment between the HS gearbox pinion shaft and the pump. Modify the cold alignment.
- Coupling Imbalance: Eccentricity of the coupling spacer from the coupling mounting center line.
- Thermal growth between the pump shaft and the HS gearbox pinion.
- Verify the radial position of the coupling spacer for potential eccentricity that could lead to imbalance forces.




March 2011 Vibration Data

Alpha FWP Testing – Root Cause Detection

Verified/ corrected the misalignment of the entire train



Tri-land bearings (7 mils diametral clearance)




Reduced the torque OB pump

Adjusted the turn-buckles as per OEM's spec

- Installed temporary thermocouples at the IB and OB faces of the pump casing to measure transient temperature field
- Installed temporary laser instrumentation to measure thermal growth of the pump casing in the axial and horizontal directions
- Modified the warm-up procedure to alleviate rubbing during high thermal gradients within the pump (reduced seal cooling water flow rate from 10 to 5 GPM).


GB HS DE - Shaft Vibration




Pump - Shaft Vibration

X 
Y 

Pump Inboard Bearing






Pump Outboard Bearing







Shaft Orbits

09:59:23 AM
03/05/2011




11:00:23 AM
03/05/2011



View from East (pump OBB)

GB HS DE - Shaft Movement



45th Turbomachinery
32nd Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER

September 12 -15.2016


Pump IBB - Shaft Movement

Initial Recommendations:

- TIR on V-blocks and
- FEA thermal analysis of the casing



Pump Inboard Bearing




45th Turbomachinery
32nd Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER


September 12 -15, 2016

Pump OBB - Shaft Movement




Root Cause

1st stage flow path did not allow uniform thermal expansion of the pump casing at the IB end cover. Former seal injection design allowed accumulation of condensate seal water at the bottom of the pump casing with lower temperature than the reactor feed water. This was causing distortion of the inboard cover plate and therefore internal misalignment at the IBB.



June 2012 Vibration Data FWP A/B/C Follow-Up Testing

- New rotating elements on all three pumps
- New gear set (output speed from 3,339 rpm to 3,400 rpm)



Balance drum re-dimensioned to provide unidirectional thrust load at any flow rate.
(rotor at times had been under compression towards the outboard (OB) end)

Plant EPU Project

2FWS-P1A/B/C Modified by June 2012




45th Turbomachinery
32nd Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER


September 12 -15.2016

2FWS-P1A Pump Shaft Vibration

Pump Shaft Vibration - Inboard



Pump Shaft Vibration - Outboard



Final Conclusions

1. Modifications implemented on these pumps during the outage (i.e. seal injection API plan 23) eliminated the thermal distortion effect that was causing deformation of the inboard end cover of the pump.
2. Previous seal injection design allowed accumulation of condensate seal water at the bottom of the pump casing with lower temperature than the reactor feed water. This was causing distortion of the inboard cover plate and therefore internal misalignment at the IBB.
3. The shaft vibration at the IBB used to be approximately 4.5 mils pk-pk, while the vibration at the OBB was approximately 1.0 mil pk-pk. Vibration data gathered after the outage indicated significant improvement at the IBB (2x reduction).
4. Radial proximity probe GAP voltage readings were not changing over time during the warm-up or cool-down processes, versus such changes that had been identified in previous tests.



Final Recommendations

1. Pre-installation FEA analysis (structural and thermal) would have been able to reduce risk by spotting problems before they occur (PREVENTION).
2. ODS / EMA / Continuous Monitoring Tests coupled with appropriate analysis is a powerful troubleshooting tool to identify and visually understand the most difficult vibration problems in turbomachinery and pumping systems.