


Stepper Motor: Working, principle, Application Explained

CREATED BY: OPEN2HIRE



WWW.OPEN2HIRE.COM



SWIPE →

Stepper Motors: Principles, Characteristics, Transient Performance, Maintenance

Table of Content

I. Introduction

Definition of Stepper Motors

Importance and applications of Stepper Motors

II. Working Principle of Stepper Motors

Construction of Stepper Motors

Electromagnetic and permanent magnet stepper motors

Rotating magnetic field and step angle

Full-step and half-step modes of operation

III. Characteristics of Stepper Motors

Holding torque and detent torque

Speed-torque characteristics

Resolution and accuracy

Stepping modes and stepping rates

IV. Transient Performance of Stepper Motors

Step response time and settling time

Resonance and vibration

Backlash and hysteresis

V. Maintenance of Stepper Motors

key maintenance considerations for Stepper motors

clean and lubricate Stepper motors

common issues with Stepper motors

VI. Conclusion

Recap of the main points

Final thoughts on the importance of stepping motors in various industries



open2hire


Number one online job listing

Stepper Motors: Principles, Characteristics, Transient Performance, Maintenance

I. Introduction

Definition of Stepper Motors

Stepper motors are a type of electric motor that moves in precise, small increments or steps rather than continuously. They are commonly used in industrial applications that require precise motion control, such as robotics, 3D printing, CNC machines, and automated production lines. Stepper motors have a permanent magnet rotor and a stator that is energized in a specific sequence to produce rotation. This sequence of energizing the stator is determined by the motor's controller, which sends pulses of current to the stator windings. The number of steps per revolution, or step angle, is determined by the design of the motor and its controller. Stepper motors are available in a wide range of sizes and configurations, from small, low-power motors for precision instruments to large, high-torque motors for industrial machinery.



Importance and applications of Stepper Motors

Stepper motors are widely used in various applications that require precise positioning and control. Some of the important applications of stepper motors are:

CNC Machines: Stepper motors are extensively used in computer numerical control (CNC) machines for precise positioning and control of the movement of the machine.

Robotics: Stepper motors are commonly used in robotics for precise control of the movement of robot arms, legs, or other components.

Printers: Stepper motors are used in printers to control the movement of the print head and paper feed mechanism.

Medical equipment: Stepper motors are used in various medical equipment, such as medical scanners and X-ray machines, for precise positioning and control.

Automotive: Stepper motors are used in automotive applications, such as in the fuel injection system, to control the precise amount of fuel delivered to the engine.

Industrial automation: Stepper motors are used in various industrial automation applications, such as conveyor systems, to control the movement of components.


Consumer electronics: Stepper motors are used in various consumer electronics products, such as cameras and DVD drives, for precise positioning and control.

II. Working Principle of Stepper Motors

Construction of Stepper Motors

The construction of stepper motors varies depending on the type and design of the motor. However, most stepper motors share some basic components, including a rotor, stator, and bearings.

The **rotor** is the rotating part of the motor and is typically composed of a permanent magnet



or iron core with teeth that interact with the stator's magnetic fields. The number of teeth on the rotor determines the step angle of the motor.

The **stator** is the stationary part of the motor and contains multiple poles that create magnetic fields. The stator poles are typically arranged in a circular pattern around the rotor, and the number of poles on the stator determines the number of steps per revolution.

The **bearings** support the rotor and allow it to rotate smoothly within the stator. The bearings are typically made of materials like steel or ceramic and are designed to withstand the high loads and speeds associated with stepper motor operation.

In addition to these basic components, stepper motors may also include features like gearboxes, encoders, and other accessories that enhance the motor's performance and functionality.

Electromagnetic stepper motors


Electromagnetic stepper motors, also known as variable reluctance stepper motors, are a type of stepper motor that operate by the principle of magnetic attraction. These motors consist of a rotor, stator, and a coil wound around the stator poles. The rotor is made up of soft iron and has teeth that are magnetically attracted to the stator poles.

When a current is applied to a stator winding, a magnetic field is produced that attracts the teeth of the rotor. As the rotor teeth align with the stator poles, the magnetic field pulls the rotor into alignment with the stator. As the rotor turns, the magnetic field is shifted, causing the rotor to turn in small, precise steps.

The step angle of an electromagnetic stepper motor is determined by the number of teeth on the rotor and stator. The more teeth there are, the smaller the step angle will be. The number of teeth on the rotor and stator can be adjusted to achieve the desired step angle.

Electromagnetic stepper motors have a number of advantages, including their low cost, simple construction, and precise positioning capabilities. However, they are not as efficient as other types of stepper motors and can experience issues with vibration and noise.

Permanent magnet stepper motors



In a permanent magnet stepper motor, the rotor has permanent magnets on its surface, and the stator has two pairs of coils arranged at 90-degree intervals. When current flows through the coils, it creates a magnetic field that interacts with the permanent magnets on the rotor, causing it to rotate to align with the magnetic field. The stator coils are energized in a specific sequence to create a stepwise motion of the rotor. The step angle in a permanent magnet stepper motor is determined by the number of teeth on the rotor and the number of poles on the stator. Permanent magnet stepper motors are often used in low-speed, low-torque applications where accuracy is important.

Rotating magnetic field

In stepper motors, the rotating magnetic field is the fundamental concept that enables the motor to function. The rotating magnetic field is created by energizing the motor's windings in a specific sequence. This sequence of energization produces a magnetic field that rotates around the rotor, causing it to turn.

The magnetic field can be represented as a vector that rotates around the stator axis. The speed of rotation of the magnetic field is determined by the frequency of the input pulses and the number of poles in the stator.

The equation for the rotating magnetic field is:

$$B = B_m \sin(2\pi f t + \theta)$$

where:

B = magnetic field strength

B_m = maximum magnetic field strength

f = frequency of the input pulses

t = time

θ = phase angle

Step angle

The step angle of a stepper motor is the angle through which the rotor moves for each electrical pulse received by the motor. The step angle is determined by the number of teeth on the rotor and the number of poles on the stator. It is also influenced by the type of stepper motor used, as different types have different step angles.

The equation for the step angle is:

$$\theta_{\text{step}} = 360 / (N_{\text{poles}} \times N_{\text{teeth}})$$

where:

θ_{step} = step angle

N_{poles} = number of poles in the stator

N_{teeth} = number of teeth in the rotor

By controlling the input pulse frequency and the sequence of energizing the stator windings, the stepper motor can be made to rotate in precise steps. This makes stepper motors ideal for applications that require precise control, such as in robotics, CNC machines, and 3D printers. In electromagnetic stepper motors, the step angle is typically small and can range from 0.9 degrees to 15 degrees. Permanent magnet stepper motors, on the other hand,

typically have larger step angles, ranging from 15 degrees to 90 degrees. The step angle determines the precision of the stepper motor, with smaller step angles providing higher precision.

Full-step and half-step modes of operation

Full-step and half-step are the two modes of operation used in stepper motors.

In full-step mode, the stepper motor takes a full step in one direction, and then another full step in the opposite direction, producing twice the torque of half-step mode. This mode provides high accuracy and resolution, but the stepping is not as smooth as in the half-step mode.

In the half-step mode, the stepper motor takes half steps in alternating directions, producing smoother and quieter operation than the full-step mode. However, it has lower torque and resolution than the full-step mode. The half-step mode can be useful in applications where high precision and smooth operation are required.

The choice of operating mode depends on the specific requirements of the application.

III. Characteristics of Stepper Motors

Holding torque and detent torque

Stepper motors have two types of torque - holding torque and detent torque.

Holding torque is the amount of torque that is required to hold the rotor in a specific position without any motion. The holding torque is proportional to the current that is flowing through the stator winding. The higher the current, the higher the holding torque.

Detent torque, on the other hand, is the amount of torque that is required to move the rotor from one stable position to another. It is the minimum torque required to overcome the magnetic forces of the rotor and move it to the next stable position. Detent torque is also proportional to the current that is flowing through the stator winding.

Both holding torque and detent torque are important characteristics of stepper motors and are crucial in determining the motor's performance. Higher holding torque is desired for applications that require high precision and accuracy, while lower detent torque is preferred for smoother operation and less power consumption.

Speed-torque characteristics

The speed-torque characteristic of a stepper motor is an essential parameter that defines the motor's operation. It shows the relationship between the motor's speed and the torque it can generate. The graph of speed-torque characteristics typically has two curves - one for accelerating and one for decelerating.

The torque generated by a stepper motor decreases as the speed increases. This relationship is due to the fact that stepper motors operate in a manner that requires them to change their direction and speed rapidly. This means that the torque generated by the motor is limited by the time required to switch the current in the coils.

The speed-torque characteristic curve for a stepper motor is typically nonlinear. In other words, the torque generated by the motor decreases rapidly as the speed increases. The curve usually has two distinct sections: a flat section and a falling section. The flat section is where the motor can generate its maximum torque, and the falling section is where the torque drops off rapidly as the speed increases.

The holding torque is the maximum torque that a stepper motor can generate without moving. The detent torque, on the other hand, is the torque required to move the rotor from one detent position to another. The detent position is the point where the motor is most stable and has the least amount of vibration. The detent torque is typically much lower than the holding torque.

The speed-torque characteristics of a stepper motor are affected by various factors, including the number of rotor teeth, the number of phases, and the current applied to the coils. By controlling these factors, stepper motors can be optimized for different applications.

Resolution and accuracy

Resolution refers to the smallest angular displacement that a stepper motor can produce. The resolution of a stepper motor depends on its step angle and the number of rotor teeth. The higher the number of rotor teeth and the smaller the step angle, the higher the resolution of the motor.

Accuracy refers to how closely the motor can follow the input signal. Stepper motors are open-loop systems, which means that they rely on the input signal to determine their position. Therefore, the accuracy of a stepper motor depends on the accuracy of the input signal. In practice, the accuracy of stepper motors is typically limited to a few percent of a step.

Stepping modes and stepping rates

Stepping modes refer to the ways in which the stator windings are energized to produce the step motion in a stepper motor. There are different stepping modes, including full-step, half-step, microstepping, and others.

Stepping rates refer to the frequency of the pulse signals applied to the motor to make it rotate. The stepping rate determines the speed of the motor, and it is usually measured in pulses per second (PPS) or steps per second (SPS).

The stepping mode and rate have a significant impact on the performance of the stepper motor. The full-step mode provides higher torque and accuracy but lower speed than the half-step mode. The micro stepping mode provides smoother and more precise motion but requires more complex control electronics.

The stepping rate affects the speed and stability of the motor. High stepping rates can cause resonance and vibration, leading to a reduction in accuracy and performance. The optimal stepping rate depends on the motor's characteristics, load, and control system.

IV. Transient Performance of Stepper Motors

Step response time and settling time

Stepper motors have two types of torque - holding torque and detent torque.

Holding torque is the amount of torque that is required to hold the rotor in a specific position without any motion. The holding torque is proportional to the current that is flowing through the stator winding. The higher the current, the higher the holding torque.

Detent torque, on the other hand, is the amount of torque that is required to move the rotor from one stable position to another. It is the minimum torque required to overcome the magnetic forces of the rotor and move it to the next stable position. Detent torque is also proportional to the current that is flowing through the stator winding.

Both holding torque and detent torque are important characteristics of stepper motors and are crucial in determining the motor's performance. Higher holding torque is desired for applications that require high precision and accuracy, while lower detent torque is preferred for smoother operation and less power consumption.

Resonance and vibration

Stepper motors are susceptible to **resonance and vibration**, which can negatively impact their performance. Resonance occurs when the natural frequency of the motor matches the frequency of the applied step pulses. This can cause the motor to vibrate excessively and lose steps, resulting in reduced accuracy and speed.

To prevent resonance, stepper motors are designed with damping techniques such as micro stepping and current limiting. Micro stepping involves dividing the full step into smaller micro steps, which reduces the step size and frequency, and can help avoid resonance. Current limiting reduces the amount of current flowing through the motor windings, which can also help prevent resonance and improve stability.

Additionally, stepper motors may be mounted on vibration-damping mounts or isolation pads to further reduce vibrations and improve their overall performance.

Backlash and hysteresis

Backlash and hysteresis are two important factors that affect the performance of stepper motors.

Backlash refers to the amount of lost motion or play in a mechanical system. In the context of stepper motors, it refers to the small amount of motion that occurs before the motor's rotor starts to move. This can cause inaccuracies in the motor's movement and affect its precision. Backlash can be minimized by using high-quality bearings and reducing the amount of clearance between the motor and the load.

Hysteresis, on the other hand, is the tendency of a material to lag behind an applied force. In stepper motors, it refers to the small amount of rotational lag that occurs between the motor's input signal and its output shaft. This can cause inaccuracies in the motor's movement and affect its precision. Hysteresis can be minimized by using high-quality materials and optimizing the motor's design.

Overall, minimizing backlash and hysteresis are important for achieving precise and accurate movement in stepper motors.

V. Maintenance of Stepper Motors

key maintenance considerations for Stepper motors

Regular maintenance of stepper motors is important to ensure their longevity and optimal performance. Here are some key maintenance considerations for stepper motors:

Cleaning: Stepper motors should be kept clean to prevent the accumulation of dirt and dust, which can interfere with the motor's operation. Regular cleaning with a soft cloth or brush can help prevent this buildup.

Lubrication: The bearings and other moving parts of stepper motors should be lubricated regularly to reduce friction and prevent wear and tear. However, it is important to use the right type of lubricant to avoid damaging the motor.

Checking for loose connections: Stepper motors rely on electrical connections to function, so it is important to regularly check for loose connections, frayed wires, or other issues that can cause electrical problems.

Calibration: Stepper motors may require occasional calibration to ensure that they are functioning properly. This may involve adjusting the position of the motor or the timing of the electrical pulses that drive it.

Replacement of worn parts: Over time, stepper motors may experience wear and tear on certain parts, such as the bearings or gears. These parts should be replaced as necessary to ensure optimal performance and prevent further damage to the motor.

Storage: If stepper motors are not in use for an extended period of time, they should be stored in a dry, cool place to prevent damage from moisture or extreme temperatures.

By following these maintenance considerations, stepper motors can continue to operate at peak performance and provide reliable service for years to come.

common issues with Stepper motors

Some common issues with stepper motors include overheating, misalignment, damaged or worn out bearings, loose connections, and electronic failures. Overheating can occur when the motor is operated at a high current or for extended periods of time without proper cooling. Misalignment can cause excessive wear and tear on the motor, leading to reduced performance and premature failure. Damaged or worn out bearings can cause noise, vibration, and reduced efficiency. Loose connections can lead to intermittent operation or complete motor failure. Electronic failures can occur due to factors such as power surges, electrical noise, or improper handling of the motor. Regular maintenance, such as cleaning, lubrication, and inspection, can help prevent these issues and extend the lifespan of the motor.

VI. Conclusion

In conclusion, stepper motors are widely used in various applications due to their precise positioning capabilities, ease of control, and low cost. The principle of operation of stepper motors is based on the creation of a rotating magnetic field, which causes the motor to rotate in discrete steps. Stepper motors can be classified into two main categories: electromagnetic and permanent magnet. They have various characteristics such as holding torque, detent torque, speed-torque characteristics, resolution, accuracy, stepping modes, stepping rates, step response time, settling time, resonance, and vibration. It is important to consider maintenance and common issues when using stepper motors to ensure optimal performance and longevity. The use of stepper motors has become increasingly popular in various industries, including robotics, automation, medical equipment, and many others, demonstrating their versatile nature and wide range of applications.

Final thoughts on the importance of stepping motors in various industries

Stepper motors play a crucial role in a variety of industries, from manufacturing to medical equipment. Their precise and reliable motion control capabilities make them ideal for applications that require high accuracy and repeatability. The availability of different types of stepper motors with various characteristics and performance parameters has enabled engineers and designers to select the appropriate stepper motor for their specific application needs.

In addition to their performance benefits, stepper motors also offer advantages in terms of ease of use, low cost, and low maintenance requirements. This makes them a popular choice for both small and large-scale applications.

Overall, the importance of stepper motors in various industries cannot be overstated. As technology continues to advance and new applications emerge, stepper motors will undoubtedly continue to be a critical component in the motion control industry.

